

From 35mm door thickness.
The handle spindle should at least engage 20mm into the handle.